

# Inspection Result Report

## Ins Info

Product Name	Lot Num	Lot Unit	Ins Start	Ins End	Oper	Confirm
ARG-Round 2	Test 3	0 EA	2018 / 7 / 26 17 : 35	2018 / 7 / 26 17 : 37	system	

## Ins Grade

Top Ins Grade		Side Ins Grade	
Normal Dark Dirty	2 grade	Side Dark Dirty	4 grade
Carve Dark Dirty	7 grade	Side blurred Stain	4 grade
Edge Dark Dirty	2 grade	Side Edge Defect	4 grade 3 grade
Normal blurred Stain	5 grade	Thickness Defect	-0.51 mm +0.54 mm
Edge blurred Stain	5 grade	Color Stain	6 grade
Color Stain	6 grade	3D Cam Ins Grade	
Other Ins Grade		Shape Break Except Edge	0.114 mm
Engrave Erase	20 grade	Edge Shape Break	0.18 mm
Engrave Distinguish G	2 grade	Carve Erase	20 %
Color	3 grade		

## Ins Result

Quantity	
Total Quantity Ins	9,909 EA
Total Quantity Good	9,852 EA
Total Quantity Defect	57 EA
Defect Ratio	0.58 %
Yield	99.42 %

Done By :

Checked By:

Reviewed By :

Date :


Date :

Date :


## Defects Categorigation And Result

Defect Item	Quantity	Rate	Defect Item	Quantity	Rate
Color Defect (R)	0	0.00	Print(Engrave) is Erased	0	0.00
Color Defect(G)	0	0.00	Tablet Outside Break	41	71.93
Color Defect (B)	0	0.00	Cleared Engraving or Incorrect	2	3.51
Dark spot	1	1.75	Color Spot or Chipped Coating	1	1.75
Sticking	0	0.00	Corner-External Damage	0	0.00
Blur Stains	1	1.75	Corner-Dark Spot	1	1.75
Side Dark Spot	9	15.79	Side Edge Defect	0	0.00
Side Blur Stain	1	1.75	Color Dot Defect	0	0.00
Corner-Blur Spot	0	0.00	Thin Tablet	0	0.00
Tablet Piece	0	0.00	Thick tablet	0	0.00
			Total Quantity	57	100.00

## Inspection Result Chart



## Inspection Speed Information



Done By :

Checked By:

Reviewed By :

Date :

Date :

Date :